

REPORT OF DAMAGE TO COMPANY-OWNED PROPERTY

(NOTE: Please refer to the bottom of this form before proceeding with completion.)

Part A

Owner of Property: MDU District: WILLISTON Town: Ross, ND
 Time of Damage: 2:03 PM Date: 4/30/2014
 Name of Location Where Damage Occurred: CENTRAL AVE ROSS
 Location of Damaged Property: CENTRAL AVE ROSS
 Rural Location: _____
 Estimated Amount of Loss: _____ First Responder Order No. (If applicable): MDUG-20140430-01624
 CC&B Account # (If Applicable): _____ MDU Service Order No. (If applicable): MDUG-20140501-01676
 If damaged meter, meter number: _____ Additional Work Order (If applicable): _____
 Description and Cause of Loss or Damage Type of meter: _____
Tore line in half with a trackhoe

Part B

Did Loss or Damage Originate on our Premises? (If no, Explain): N

If an Explosion, did a Fire Ensur? N (How was Fire Extinguished?)

If Electrical Property is Involved, Fill in the Following Supplemental Data:

Type of Equipment Involved: _____
 Damage caused by Electrical Arcing, Short Circuit or Other Failure, Give Approximate Cause

If Electrical, Did a Fire Ensur? N

Part C

If damage was caused by excavation, was location of our facilities requested prior to digging? Y
 Location requested by: NORTHERN EXCAVATION Time: 11:33 AM Date: 4/21/2013
 Line Locate Number: 14030557
 Company property located on:
 Damage notification by: NORTHERN EXCAVATION Time: 2:03 PM Date: 4/30/2014
 Was damager a subcontractor: N If yes, for whom: _____

Who to bill for damages:

Name of who to Bill: NORTHERN EXCAVATION Name of Equipment Operator: JODY MITTLEIDER
 Address of who to Bill: PO BOX 1108 Type of equipment: TRACKHOE
JAMESTOWN ND 58402 Operator's Address: _____
 Phone # of who to Bill: 701-252-5967 Operator's Phone #: 701-269-9679
 Name of Insurer: _____
 Insurance Policy #: _____ Was a Police Report made: N If yes, please attach report

- | | | | | | | | |
|----|-------------|------------------|----------|----|---------------------------|------------------|----------|
| 36 | PU-14-671 | Filed 06/30/2015 | Pages: 2 | 39 | GS-13-885 | Filed 06/30/2015 | Pages: 2 |
| | Exhibit A10 | | | | Exhibit A10 | | |
| | | | | | Public Service Commission | | |
| 39 | GS-14-230 | Filed 06/30/2015 | Pages: 2 | | | | |
| | Exhibit A10 | | | | | | |
| 39 | GS-14-229 | Filed 06/30/2015 | Pages: 2 | | | | |
| | Exhibit A10 | | | | | | |
| 38 | GS-13-886 | Filed 06/30/2015 | Pages: 2 | 38 | GS-13-884 | Filed 06/30/2015 | Pages: 2 |
| | Exhibit A10 | | | | Exhibit A10 | | |



REPORT OF DAMAGE TO COMPANY-OWNED PROPERTY

Others involved in Property Damage:

<u>Names of Persons Involved</u>	<u>Address</u>	<u>Phone Number</u>
----------------------------------	----------------	---------------------

Witnesses to Property Damage:

<u>Names of Witnesses</u>	<u>Address</u>	<u>Phone Number</u>
---------------------------	----------------	---------------------

In case of line break, complete the following:

					<u>Time</u>	<u>Date</u>
Decatherms of gas to bill: 5.3 mcf	Size of hole(in): 1IN	Time line blew: 20MIN				4/30/2014

Part D

<u>Names of Persons Injured</u>	<u>Address</u>	<u>Extent of Injury</u>
---------------------------------	----------------	-------------------------

Person Filling Out Form: Dana Baxter

Date: 5/2/2014

Approved By: _____

Date: _____

Instructions

Email this completed form to MDURA - Accounts Receivable: MDURA.AccountsReceivable@mdu.com

Use this form to make an immediate preliminary report of all damage to or loss of company-owned property:

If damage is caused by any of the following, complete Parts A, B, & D, if applicable.

- 1) Fire, lightning, inherent explosion, implosion, windstorm, tornado, flood, electrical arcing, short circuit, hail, riot and civil commotion, vandalism, malicious mischief, aircraft, or smoke damage.
- 2) An accident to boilers and/or machinery (an accident being a sudden and accidental breakdown of an object or part of an object).
- 3) Loss of or damage to property during the physical process of installation, movement or dismantling including while awaiting installation.

If damage was caused by others, complete Parts A, C & D, if applicable.

Name	Employee #	Hours	Unit #	Hours/Miles
Faber		2		
baxter		3.5		
colebank		2.5		
Faber		1.5 OT		
colebank		1OT		
baxter		1 OT		
unit 6116			6116	144
bucket truck				12

5.3 x 1.13064 = 5.8992392 x 6.749 = \$39.81