

-Info-Public Service Commission

From: Aron Anderson <aanderson@solasenergyconsulting.com>
Sent: Friday, August 12, 2016 12:58 PM
To: Lein, Jerry R.; 'sgarry@carlsonmccain.com'; 'thartleben@carlsonmccain.com'; -Info-Public Service Commission
Cc: Jed Dailey; Deron Lawrence; Cindy Whitney; Evelyn Carpenter; Ryan Hartleben; Jon Johnson
Subject: Sunflower Wind Project Weekly Construction Report - Case Number: PU-14-105
Attachments: Sunflower Wind Project Construction Update 8.12.16.pdf; Stark County Turbine Foundation Rebar Inspection Forms.pdf; Stark County Foundation Inspection Signoff.pdf

Jerry,

See attached construction weekly report for week ending 8/12/16 on the Sunflower Wind Project. Also, see attached Stark County rebar inspection and foundation signoff for turbines 1-8, 48 and 49 for your records. These are all the turbines located in Stark County. Please let me know if you have any questions.

Thank You,

Aron Anderson
Senior Project Manager
Solas Energy Consulting US Inc.
Mobile: (612) 599-4251
Email: aanderson@solasenergyconsulting.com

97 **PU-14-105** Filed: 8/12/2016 Pages: 31
Rebar inspection and foundation signoff for turbines in Stark County

Trevor Beck

From: North Dakota <wo@iworq.net>
Sent: Wednesday, July 20, 2016 2:44 PM
To: Trevor Beck
Subject: from North Dakota for Permit # 150076

Follow Up Flag: Follow up
Flag Status: Flagged

Tower 1 approved for pour

STARK COUNTY, ND BUILDING INSPECTION

51 3rd St E
 Dickinson, ND 58601
Phone: 701-842-2120

Property Address: _____ Permit #: 150076
 Subdivision: Sunflower Wind Project T-1 Lot #: _____ Date: 7/20/2016
 Name: Trevor Beck Phone #: 763-287-5180 Time: 10:00 a.m. MDT

INSPECTIONS	RESULT	SPECIAL COMMENTS	UNABLE TO MAKE INSPECTION BECAUSE
TYPE Initial Inspection		<input type="checkbox"/> Prior Violation Not Corrected <input type="checkbox"/> Engineering Required Item # _____ <input type="checkbox"/> Work Incomplete <input checked="" type="checkbox"/> Ok to Proceed without re-inspection <input type="checkbox"/> Other	<input type="checkbox"/> Approved Plan/Permit not Available <input type="checkbox"/> Building Not Identified <input type="checkbox"/> Building Locked or Work Inaccessible <input type="checkbox"/> Cannot locate structure <input type="checkbox"/> Party Missed Appointment Time: _____
INSPECTIONS Sub-Rough	Approved Correction Required Re-Inspection Requested	COMMENTS:	
		All rebar appears to be in place as per the design. All bars are tied securely in place.	
		Lapped and tied per design.	
		No issues or concerns.	
		Ok to pour.	
1. Excavation	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
2. Footings	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
3. Foundation	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
4. Mechanical	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
5. Other Pedestal Cage	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Rough			
6. Building	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
7. Mechanical	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
8. Gas Line	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9. Framing	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Truss Plans On-Site	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Fire Wall Inspection	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Fire Suppression	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Final			
10. Building	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
11. Mechanical	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
12. Other	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
FINAL INSPECTION CHECKLIST			
<u>Electrical Final</u>	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Date:			
Certificate #			
<u>Plumbing Final</u>	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Date:			
Certificate #			
Smoke Detector Hardwired	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Approved Egress	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Address Visible	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

Trevor Beck

From: North Dakota <wo@iworq.net>
Sent: Wednesday, July 20, 2016 2:47 PM
To: Trevor Beck
Subject: from North Dakota for Permit # 150077

Follow Up Flag: Follow up
Flag Status: Flagged

Tower 2 approved to pour

STARK COUNTY, ND BUILDING INSPECTION

51 3rd St E
 Dickinson, ND 58601
Phone: 701-842-2120

Property Address: _____ Permit #: 150077
 Subdivision: Sunflower Wind Project T-2 Lot #: _____ Date: 7/20/2016
 Name: Ryan Januszewski Phone #: 763-287-5180 Time: 10:00 a.m. MDT

INSPECTIONS	RESULT	SPECIAL COMMENTS	UNABLE TO MAKE INSPECTION BECAUSE
TYPE Initial Inspection		<input type="checkbox"/> Prior Violation Not Corrected <input type="checkbox"/> Engineering Required Item # _____ <input type="checkbox"/> Work Incomplete <input checked="" type="checkbox"/> Ok to Proceed without re-inspection <input type="checkbox"/> Other	<input type="checkbox"/> Approved Plan/Permit not Available <input type="checkbox"/> Building Not Identified <input type="checkbox"/> Building Locked or Work Inaccessible <input type="checkbox"/> Cannot locate structure <input type="checkbox"/> Party Missed Appointment Time: _____
		COMMENTS:	
INSPECTIONS Sub-Rough	Approved	All rebar appears to be in place as per the design. All bars are tied securely in place.	
	Correction Required	Lapped and tied per design.	
1. Excavation	[] [] []	No issues or concerns.	
2. Footings	[X] [] []	OK to pour when forms are completed.	
3. Foundation	[X] [] []		
4. Mechanical	[] [] []		
5. Other Pedestal Cage	[X] [] []		
Rough			
6. Building	[] [] []		
7. Mechanical	[] [] []		
8. Gas Line	[] [] []		
9. Framing	[] [] []		
Truss Plans On-Site	[] [] []		
Fire Wall Inspection	[] [] []		
Fire Suppression	[] [] []		
Final			
10. Building	[] [] []		
11. Mechanical	[] [] []		
12. Other	[] [] []		
FINAL INSPECTION CHECKLIST			
Electrical Final	[] [] []		
Date:			
Certificate #			
Plumbing Final	[] [] []		
Date:			
Certificate #			
Smoke Detector Hardwired	[] [] []		
Approved Egress	[] [] []		
Address Visible	[] [] []		

Trevor Beck

From: North Dakota <wo@iworq.net>
Sent: Friday, July 22, 2016 5:23 PM
To: Trevor Beck
Subject: from North Dakota for Permit # 150078


Tower 3 approved for concrete

STARK COUNTY, ND BUILDING INSPECTION

51 3rd St E
 Dickinson, ND 58601
Phone: 701-842-2120

Property Address: Tower 3 Permit #: 150078
 Subdivision: Sunflower Wind Project T-3 Lot #: _____ Date: 7/22/2016
 Name: Trevor Beck Phone #: 774-571-5645 Time: 2:00 pm MDT

INSPECTIONS	RESULT	SPECIAL COMMENTS	UNABLE TO MAKE INSPECTION BECAUSE
TYPE Initial Inspection		<input type="checkbox"/> Prior Violation Not Corrected <input type="checkbox"/> Engineering Required Item # _____ <input type="checkbox"/> Work Incomplete <input checked="" type="checkbox"/> Ok to Proceed without re-inspection <input type="checkbox"/> Other	<input type="checkbox"/> Approved Plan/Permit not Available <input type="checkbox"/> Building Not Identified <input type="checkbox"/> Building Locked or Work Inaccessible <input type="checkbox"/> Cannot locate structure <input type="checkbox"/> Party Missed Appointment Time: _____
COMMENTS:			
		All corrections made to mat	
		Pedestal Verticals and hoop ties tied in. Ground wires connected.	
		Ok to pour.	
INSPECTIONS <u>Sub-Rough</u>	Approved Correction Required Re-Inspection Requested		
1. Excavation			
2. Footings			
3. Foundation			
4. Mechanical			
5. Other Pedestal Cage			
<u>Rough</u>			
6. Building			
7. Mechanical			
8. Gas Line			
9. Framing			
Truss Plans On-Site			
Fire Wall Inspection			
Fire Suppression			
<u>Final</u>			
10. Building			
11. Mechanical			
12. Other			
FINAL INSPECTION CHECKLIST			
<u>Electrical Final</u>			
Date:			
Certificate #			
<u>Plumbing Final</u>			
Date			
Certificate #			
Smoke Detector Hardwired			
Approved Egress			
Address Visable			
Bathroom Vents Approved			
No Interior Hazard Evident			
Fire Separation Requirements			
<u>Other Items Verified</u>			

	CJJCJ	
	CJJCJ	
		<p style="text-align: center;"></p> <hr/> <p style="text-align: center;">INSPECTOR SIGNATURE</p>

Trevor Beck

From: North Dakota <wo@iworq.net>
Sent: Friday, July 22, 2016 5:25 PM
To: Trevor Beck
Subject: from North Dakota for Permit # 150079


Tower 4 approved for concrete

STARK COUNTY, ND BUILDING INSPECTION

51 3rd St E
 Dickinson, ND 58601
 Phone: 701-842-2120

Property Address: Tower 4 Permit #: 150079
 Subdivision: Sunflower Wind Project T-4 Lot #: _____ Date: 7/22/2016
 Name: Trevor Beck Phone #: 774-571-5645 Time: 2:00 pm MDT

INSPECTIONS	RESULT	SPECIAL COMMENTS	UNABLE TO MAKE INSPECTION BECAUSE
TYPE Initial Inspection		<input type="checkbox"/> Prior Violation Not Corrected <input type="checkbox"/> Engineering Required Item # _____ <input type="checkbox"/> Work Incomplete <input checked="" type="checkbox"/> Ok to Proceed without re-inspection <input type="checkbox"/> Other	<input type="checkbox"/> Approved Plan/Permit not Available <input type="checkbox"/> Building Not Identified <input type="checkbox"/> Building Locked or Work Inaccessible <input type="checkbox"/> Cannot locate structure <input type="checkbox"/> Party Missed Appointment Time: _____
INSPECTIONS Sub-Rough	Approved	COMMENTS:	
1. Excavation	[] [] []	All rebar appears to be in place as per the design. All bars are tied securely in place.	
2. Footings	[X] [] []	Lapped and tied per design.	
3. Foundation	[X] [] []	No issues or concerns.	
4. Mechanical	[] [] []	Ok to pour.	
5. Other Pedestal Cage	[X] [] []		
Rough			
6. Building	[] [] []		
7. Mechanical	[] [] []		
8. Gas Line	[] [] []		
9. Framing	[] [] []		
Truss Plans On-Site	[] [] []		
Fire Wall Inspection	[] [] []		
Fire Suppression	[] [] []		
Final			
10. Building	[] [] []		
11. Mechanical	[] [] []		
12. Other	[] [] []		
FINAL INSPECTION CHECKLIST			
Electrical Final	[] [] []		
Date:			
Certificate #			
Plumbing Final	[] [] []		
Date			
Certificate #			
Smoke Detector Hardwired	[] [] []		
Approved Egress	[] [] []		
Address Visable	[] [] []		
Bathroom Vents Approved	[] [] []		
No Interior Hazard Evident	[] [] []		
Fire Separation Requirements	[] [] []		
Other Items Verified			

CICU CICU	
	<p style="text-align: center;"></p> <hr/> <p style="text-align: center;">INSPECTOR SIGNATURE</p>

Trevor Beck

From: North Dakota <wo@iworq.net>
Sent: Monday, July 25, 2016 7:29 PM
To: Trevor Beck
Subject: from North Dakota for Permit # 150080

Tower 5 approved

STARK COUNTY, ND BUILDING INSPECTION

51 3rd St E
 Dickinson, ND 58601
Phone: 701-842-2120

Property Address: Tower 5 Permit #: 150080
 Subdivision: Sunflower Wind Project T-5 Lot #: _____ Date: 7/25/2016
 Name: Trevor Beck Phone #: 774-571-5645 Time: 2:00 pm MDT

INSPECTIONS	RESULT	SPECIAL COMMENTS	UNABLE TO MAKE INSPECTION BECAUSE
TYPE Initial Inspection		<input type="checkbox"/> Prior Violation Not Corrected <input type="checkbox"/> Engineering Required Item # _____ <input type="checkbox"/> Work Incomplete <input checked="" type="checkbox"/> Ok to Proceed without re-inspection <input type="checkbox"/> Other	<input type="checkbox"/> Approved Plan/Permit not Available <input type="checkbox"/> Building Not Identified <input type="checkbox"/> Building Locked or Work Inaccessible <input type="checkbox"/> Cannot locate structure <input type="checkbox"/> Party Missed Appointment Time: _____
INSPECTIONS <u>Sub-Rough</u>	Approved Correction Required Re-Inspection Requested	COMMENTS:	
1. Excavation	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	All rebar appears to be in place as per the design. All bars are tied securely in place.	
2. Footings	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Lapped and tied per design.	
3. Foundation	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	One minor issue with ties on standee. Marked with green paint to be corrected before pour.	
4. Mechanical	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	OK to pour once corrected.	
5. Other Pedestal Cage	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
<u>Rough</u>			
6. Building	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
7. Mechanical	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
8. Gas Line	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9. Framing	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Truss Plans On-Site	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Fire Wall Inspection	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Fire Suppression	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
<u>Final</u>			
10. Building	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
11. Mechanical	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
12. Other	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
FINAL			
INSPECTION CHECKLIST			
<u>Electrical Final</u>	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Date:			
Certificate #			
<u>Plumbing Final</u>	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Date:			
Certificate #			
Smoke Detector Hardwired	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Approved Egress	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Address Visible	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Bathroom Vents Approved	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
No Interior Hazard Evident	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Fire Separation Requirements	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
<u>Other Items Verified</u>			

CICD CICD	
	<p style="text-align: center;"><i>Robert J. Gray</i></p> <hr/> <p style="text-align: center;">INSPECTOR SIGNATURE</p>

Trevor Beck

From: North Dakota <wo@iworq.net>
Sent: Monday, July 25, 2016 7:31 PM
To: Trevor Beck
Subject: from North Dakota for Permit # 150081

Tower 6 approved for pour.

STARK COUNTY, ND BUILDING INSPECTION

51 3rd St E
 Dickinson, ND 58601
 Phone: 701-842-2120

Property Address: Tower 6 Permit #: 150081
 Subdivision: Sunflower Wind Project T-6 Lot #: _____ Date: 7/25/2016
 Name: Trevor Beck Phone #: 774-571-5645 Time: 2:00 pm MDT

INSPECTIONS	RESULT	SPECIAL COMMENTS	UNABLE TO MAKE INSPECTION BECAUSE
TYPE Initial Inspection		<input type="checkbox"/> Prior Violation Not Corrected <input type="checkbox"/> Engineering Required Item # _____ <input type="checkbox"/> Work Incomplete <input checked="" type="checkbox"/> Ok to Proceed without re-inspection <input type="checkbox"/> Other	<input type="checkbox"/> Approved Plan/Permit not Available <input type="checkbox"/> Building Not Identified <input type="checkbox"/> Building Locked or Work Inaccessible <input type="checkbox"/> Cannot locate structure <input type="checkbox"/> Party Missed Appointment Time: _____
INSPECTIONS <u>Sub-Rough</u>	Approved Correction Required Re-Inspection Requested	COMMENTS:	
1. Excavation	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	All rebar appears to be in place as per the design. All bars are tied securely in place.	
2. Footings	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Lapped and tied per design.	
3. Foundation	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	No issues or concerns.	
4. Mechanical	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	OK to pour.	
5. Other Pedestal Cage	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
<u>Rough</u>			
6. Building	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
7. Mechanical	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
8. Gas Line	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9. Framing	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Truss Plans On-Site	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Fire Wall Inspection	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Fire Suppression	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
<u>Final</u>			
10. Building	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
11. Mechanical	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
12. Other	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
FINAL INSPECTION CHECKLIST			
<u>Electrical Final</u>	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Date:			
Certificate #			
<u>Plumbing Final</u>	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Date			
Certificate #			
Smoke Detector Hardwired	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Approved Egress	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Address Visible	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Bathroom Vents Approved	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
No Interior Hazard Evident	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Fire Separation Requirements	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
<u>Other Items Verified</u>			

CICCI CICCI	
	<p style="text-align: center;"><i>Robert J. Gray</i></p> <hr/> <p style="text-align: center;">INSPECTOR SIGNATURE</p>

Trevor Beck

From: North Dakota <wo@iworq.net>
Sent: Wednesday, July 27, 2016 7:49 PM
To: Trevor Beck
Subject: from North Dakota for Permit # 150082

Tower 7

STARK COUNTY, ND BUILDING INSPECTION

51 3rd St E
 Dickinson, ND 58601
Phone: 701-842-2120

Property Address: Tower 7 Permit #: 150082
 Subdivision: Sunflower Wind Project T-7 Lot #: _____ Date: 7/27/2016
 Name: Trevor Beck Phone #: 774-571-5645 Time: 3:00 pm MDT

INSPECTIONS	RESULT	SPECIAL COMMENTS	UNABLE TO MAKE INSPECTION BECAUSE
TYPE Initial Inspection		<input type="checkbox"/> Prior Violation Not Corrected <input type="checkbox"/> Engineering Required Item # _____ <input type="checkbox"/> Work Incomplete <input checked="" type="checkbox"/> Ok to Proceed without re-inspection <input type="checkbox"/> Other	<input type="checkbox"/> Approved Plan/Permit not Available <input type="checkbox"/> Building Not Identified <input type="checkbox"/> Building Locked or Work Inaccessible <input type="checkbox"/> Cannot locate structure <input type="checkbox"/> Party Missed Appointment Time: _____
INSPECTIONS <u>Sub-Rough</u>	Approved Correction Required Re-Inspection Requested	COMMENTS: All rebar appears to be in place as per the design. All bars are tied securely in place. Lapped and tied per design. No issues or concerns. Ok to pour.	
1. Excavation <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 2. Footings <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 3. Foundation <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 4. Mechanical <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 5. Other Pedestal Cage <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <u>Rough</u> 6. Building <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 7. Mechanical <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 8. Gas Line <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 9. Framing <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Truss Plans On-Site <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Fire Wall Inspection <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Fire Suppriession <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <u>Final</u> 10. Building <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 11. Mechanical <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 12. Other <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> FINAL INSPECTION CHECKLIST <u>Electrical Final</u> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Date: _____ Certificate # _____ <u>Plumbing Final</u> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Date _____ Certificate # _____ Smoke Detector Hardwired <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Approved Egress <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Address Visable <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Bathroom Vents Approved <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> No Interior Hazard Evident <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Fire Seperation Requirements <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <u>Other Items Verified</u>			

CICCI CICCI	
	<p style="text-align: center;"><i>Robert J. Brad</i></p> <hr/> <p style="text-align: center;">INSPECTOR SIGNATURE</p>

CICU CICU	
	<p style="text-align: center;"><i>Robert J. Brad</i></p> <hr/> <p style="text-align: center;">INSPECTOR SIGNATURE</p>

Trevor Beck

From: North Dakota <wo@iworq.net>
Sent: Thursday, August 04, 2016 9:39 PM
To: Trevor Beck
Subject: from North Dakota for Permit # 150084

Follow Up Flag: Follow up
Flag Status: Flagged

Tower 48 approved for concrete

STARK COUNTY, ND BUILDING INSPECTION

51 3rd St E
 Dickinson, ND 58601
 Phone: 701-842-2120

Property Address: _____ Permit #: 150084
 Subdivision: Sunflower Wind Project T-48 Lot #: _____ Date: 8/4/2016
 Name: Santiago Phone #: 763-287-3717 Time: 9:15 a.m. MDT

INSPECTIONS	RESULT	SPECIAL COMMENTS	UNABLE TO MAKE INSPECTION BECAUSE
TYPE Initial Inspection		<input type="checkbox"/> Prior Violation Not Corrected <input type="checkbox"/> Engineering Required Item # _____ <input type="checkbox"/> Work Incomplete <input checked="" type="checkbox"/> Ok to Proceed without re-inspection <input type="checkbox"/> Other	<input type="checkbox"/> Approved Plan/Permit not Available <input type="checkbox"/> Building Not Identified <input type="checkbox"/> Building Locked or Work Inaccessible <input type="checkbox"/> Cannot locate structure <input type="checkbox"/> Party Missed Appointment Time: _____
INSPECTIONS Sub-Rough	Approved	COMMENTS:	
1. Excavation	[] [] []	All rebar appears to be in place as per the design. All bars are tied securely in place.	
2. Footings	[X] [] []	Lapped and tied per design.	
3. Foundation	[X] [] []	No issues or concerns.	
4. Mechanical	[] [] []	All corrections made during inspection.	
5. Other Pedestal Cage	[X] [] []	OK to pour.	
Rough			
6. Building	[] [] []		
7. Mechanical	[] [] []		
8. Gas Line	[] [] []		
9. Framing	[] [] []		
Truss Plans On-Site	[] [] []		
Fire Wall Inspection	[] [] []		
Fire Suppression	[] [] []		
Final			
10. Building	[] [] []		
11. Mechanical	[] [] []		
12. Other	[] [] []		
FINAL INSPECTION CHECKLIST			
Electrical Final	[] [] []		
Date:			
Certificate #			
Plumbing Final	[] [] []		
Date			
Certificate #			
Smoke Detector Hardwired	[] [] []		
Approved Egress	[] [] []		
Address Visible	[] [] []		

Bathroom Vents Approved [] [] []
No Interior Hazard Evident [] [] []
Fire Separation Requirements [] [] []
Other Items Verified

[] [] []

[] [] []



INSPECTOR SIGNATURE

Trevor Beck

From: North Dakota <wo@iworq.net>
Sent: Thursday, August 04, 2016 9:51 PM
To: Trevor Beck
Subject: from North Dakota for Permit # 150085

Follow Up Flag: Follow up
Flag Status: Flagged

Tower 49 approved for concrete

STARK COUNTY, ND BUILDING INSPECTION

51 3rd St E
 Dickinson, ND 58601
 Phone: 701-842-2120

Property Address: _____ Permit #: 150085
 Subdivision: Sunflower Wind Project T-49 Lot #: _____ Date: 8/4/2016
 Name: Trevor Beck Phone #: 774-571-5645 Time: 9:15 a.m. MDT

INSPECTIONS	RESULT	SPECIAL COMMENTS	UNABLE TO MAKE INSPECTION BECAUSE
<u>TYPE</u> Initial Inspection		<input type="checkbox"/> Prior Violation Not Corrected <input type="checkbox"/> Engineering Required Item # _____ <input type="checkbox"/> Work Incomplete <input checked="" type="checkbox"/> Ok to Proceed without re-inspection <input type="checkbox"/> Other	<input type="checkbox"/> Approved Plan/Permit not Available <input type="checkbox"/> Building Not Identified <input type="checkbox"/> Building Locked or Work Inaccessible <input type="checkbox"/> Cannot locate structure <input type="checkbox"/> Party Missed Appointment Time: _____
<u>INSPECTIONS</u> <u>Sub-Rough</u>	Approved Correction Required Re-inspection Requested	COMMENTS:	
1. Excavation	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	All rebar appears to be in place as per the design. All bars are tied securely in place.	
2. Footings	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Lapped and tied per design.	
3. Foundation	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	No issues or concerns.	
4. Mechanical	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	All corrections made during inspection.	
5. Other Pedestal Cage	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	OK to pour.	
<u>Rough</u>			
6. Building	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
7. Mechanical	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
8. Gas Line	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9. Framing	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Truss Plans On-Site	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Fire Wall Inspection	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Fire Suppression	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
<u>Final</u>			
10. Building	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
11. Mechanical	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
12. Other	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
FINAL INSPECTION CHECKLIST			
<u>Electrical Final</u>	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Date:			
Certificate #			
<u>Plumbing Final</u>	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Date:			
Certificate #			
Smoke Detector Hardwired	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Approved Egress	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Address Visible	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

Trevor Beck

From: North Dakota <wo@iworq.net>
Sent: Thursday, August 04, 2016 9:49 PM
To: Trevor Beck
Subject: North Dakota Permit # 150076

Follow Up Flag: Follow up
Flag Status: Flagged

This verifies Permit #15-0084S is closed and inspections have been completed. Should you have any questions, feel free to contact me for more information. I hope this is sufficient for your records. Bobbi Strait

Permit Information

Date 10/19/2015
Permit Number 150076
Stark Permit Number 15-076S
Permit Type Commercial
Date of Issuance 9/28/2015
Expiration Date
Project Title Sunflower Wind Project T-1
Project Description Wind Turbine
Address Near 40th St SW & County Road 90
Applicant Name Trevor Beck
Applicant Address
Applicant Phone 774-571-5645
Email address
On Site Contact Ryan Januszewski
On-Site Contact Phone 763-287-5180
Declaration Licensed Contractor Declaration
Zoning Notes
Building Notes
Fire Notes
Zoning Approved 9/25/2015
Building Approved 9/25/2015
Fire Approved
Square Feet 0
Project Value 177251
Date Finaled
City Hebron
Parcel Number
Plan Review Fee 919.67
Inspection Fee 1414.88
Total Fee 2334.55
Fee Issue Date 9/24/2015
Sprinkler System Required
Occupancy Group
Construction Type
Zone
Occupant Load
Status Closed
Assigned To Bobbi Strait

Uploaded Files		[Upload File]
Date	File	

Trevor Beck

From: North Dakota <wo@iworq.net>
Sent: Thursday, August 04, 2016 9:49 PM
To: Trevor Beck
Subject: North Dakota Permit # 150077

Follow Up Flag: Follow up
Flag Status: Flagged

This verifies Permit #15-0084S is closed and inspections have been completed. Should you have any questions, feel free to contact me for more information. I hope this is sufficient for your records. Bobbi Strait

Permit Information

Date 10/19/2015
Permit Number 150077
Stark Permit Number 15-077S
Permit Type Commercial
Date of Issuance 9/28/2015
Expiration Date
Project Title Sunflower Wind Project T-2
Project Description Wind Turbine
Address Near 40th St SW & County Road 90
Applicant Name Trevor Beck
Applicant Address
Applicant Phone 774-571-5645
Email address
On Site Contact Trevor Beck
On-Site Contact Phone 774-571-5645
Declaration Licensed Contractor Declaration
Zoning Notes
Building Notes
Fire Notes
Zoning Approved 9/25/2015
Building Approved 9/25/2015
Fire Approved
Square Feet 0
Project Value 177251
Date Finaled
City Hebron
Parcel Number
Plan Review Fee 919.67
Inspection Fee 1414.88
Total Fee 2334.55
Fee Issue Date 9/24/2015
Sprinkler System Required
Occupancy Group U
Construction Type
Zone
Occupant Load
Status Closed
Assigned To Bobbi Strait

Uploaded Files		[Upload File]
Date	File	

Trevor Beck

From: North Dakota <wo@iworq.net>
Sent: Thursday, August 04, 2016 9:48 PM
To: Trevor Beck
Subject: North Dakota Permit # 150078

Follow Up Flag: Follow up
Flag Status: Flagged

This verifies Permit #15-0084S is closed and inspections have been completed. Should you have any questions, feel free to contact me for more information. I hope this is sufficient for your records. Bobbi Strait

Permit Information

Date 10/19/2015
Permit Number 150078
Stark Permit Number 15-078S
Permit Type Commercial
Date of Issuance 9/28/2015
Expiration Date
Project Title Sunflower Wind Project T-3
Project Description Wind Turbine
Address Near 40th St SW & County Road 90
Applicant Name Trevor Beck
Applicant Address
Applicant Phone 774-571-5645
Email address
On Site Contact Trevor Beck
On-Site Contact Phone 774-571-5645
Declaration Licensed Contractor Declaration
Zoning Notes
Building Notes
Fire Notes
Zoning Approved 9/25/2015
Building Approved 9/25/2015
Fire Approved
Square Feet 0
Project Value 177251
Date Finaled
City Hebron
Parcel Number
Plan Review Fee 919.67
Inspection Fee 1414.88
Total Fee 2334.55
Fee Issue Date 9/24/2015
Sprinkler System Required
Occupancy Group U
Construction Type
Zone
Occupant Load
Status Closed
Assigned To Bobbi Strait

Uploaded Files

[Upload File]

Date

File

Trevor Beck

From: North Dakota <wo@iworq.net>
Sent: Thursday, August 04, 2016 9:47 PM
To: Trevor Beck
Subject: North Dakota Permit # 150079

Follow Up Flag: Follow up
Flag Status: Flagged

This verifies Permit #15-0084S is closed and inspections have been completed. Should you have any questions, feel free to contact me for more information. I hope this is sufficient for your records. Bobbi Strait

Permit Information

Date	10/19/2015
Permit Number	150079
Stark Permit Number	15-079S
Permit Type	Commercial
Date of Issuance	9/28/2015
Expiration Date	
Project Title	Sunflower Wind Project T-4
Project Description	Wind Turbine
Address	Near 40th St SW & County Road 90
Applicant Name	Trevor Beck
Applicant Address	
Applicant Phone	774-571-5645
Email address	
On Site Contact	Ryan Januszewski
On-Site Contact Phone	763-287-5180
Declaration	Licensed Contractor Declaration
Zoning Notes	
Building Notes	
Fire Notes	
Zoning Approved	9/25/2015
Building Approved	9/25/2015
Fire Approved	
Square Feet	0
Project Value	177251
Date Finaled	
City	Hebron
Parcel Number	
Plan Review Fee	919.67
Inspection Fee	1414.88
Total Fee	2334.55
Fee Issue Date	9/24/2015
Sprinkler System Required	
Occupancy Group	U
Construction Type	
Zone	
Occupant Load	
Status	Closed
Assigned To	Bobbi Strait

Uploaded Files

[Upload File]

Date	File
------	------

Trevor Beck

From: North Dakota <wo@iworq.net>
Sent: Thursday, August 04, 2016 9:47 PM
To: Trevor Beck
Subject: North Dakota Permit # 150080

Follow Up Flag: Follow up
Flag Status: Flagged

This verifies Permit #15-0084S is closed and inspections have been completed. Should you have any questions, feel free to contact me for more information. I hope this is sufficient for your records. Bobbi Strait

Permit Information

Date 10/19/2015
Permit Number 150080
Stark Permit Number 15-080S
Permit Type Commercial
Date of Issuance 9/28/2015
Expiration Date
Project Title Sunflower Wind Project T-5
Project Description Wind Turbine
Address Near 40th St SW & County Road 90
Applicant Name Trevor Beck
Applicant Address
Applicant Phone 774-571-5645
Email address
On Site Contact Ryan Januszewski
On-Site Contact Phone 763-287-5180
Declaration Licensed Contractor Declaration
Zoning Notes
Building Notes
Fire Notes
Zoning Approved 9/25/2015
Building Approved 9/25/2015
Fire Approved
Square Feet 0
Project Value 177251
Date Finaled
City Hebron
Parcel Number
Plan Review Fee 919.67
Inspection Fee 1414.88
Total Fee 2334.55
Fee Issue Date 9/24/2015
Sprinkler System Required
Occupancy Group U
Construction Type
Zone
Occupant Load
Status Closed
Assigned To Bobbi Strait

Uploaded Files		[Upload File]
Date	File	

Trevor Beck

From: North Dakota <wo@iworq.net>
Sent: Thursday, August 04, 2016 9:46 PM
To: Trevor Beck
Subject: North Dakota Permit # 150081

Follow Up Flag: Follow up
Flag Status: Flagged

This verifies Permit #15-0084S is closed and inspections have been completed. Should you have any questions, feel free to contact me for more information. I hope this is sufficient for your records. Bobbi Strait

Permit Information

Date 10/19/2015
Permit Number 150081
Stark Permit Number 15-081S
Permit Type Commercial
Date of Issuance 9/28/2015
Expiration Date
Project Title Sunflower Wind Project T-6
Project Description Wind Turbine
Address Near 40th St SW & County Road 90
Applicant Name Trevor Beck
Applicant Address
Applicant Phone 774-571-5645
Email address
On Site Contact Ryan Januszewski
On-Site Contact Phone 763-287-5180
Declaration Licensed Contractor Declaration
Zoning Notes
Building Notes
Fire Notes
Zoning Approved 9/25/2015
Building Approved 9/25/2015
Fire Approved
Square Feet 0
Project Value 177251
Date Finaled
City Hebron
Parcel Number
Plan Review Fee 919.67
Inspection Fee 1414.88
Total Fee 2334.55
Fee Issue Date 9/24/2015
Sprinkler System Required
Occupancy Group U
Construction Type
Zone
Occupant Load
Status Closed
Assigned To Bobbi Strait

Uploaded Files		[Upload File]
Date	File	

Trevor Beck

From: North Dakota <wo@iworq.net>
Sent: Thursday, August 04, 2016 9:46 PM
To: Trevor Beck
Subject: North Dakota Permit # 150082

Follow Up Flag: Follow up
Flag Status: Flagged

This verifies Permit #15-0084S is closed and inspections have been completed. Should you have any questions, feel free to contact me for more information. I hope this is sufficient for your records. Bobbi Strait

Permit Information

Date 10/19/2015
Permit Number 150082
Stark Permit Number 15-082S
Permit Type Commercial
Date of Issuance 9/28/2015
Expiration Date
Project Title Sunflower Wind Project T-7
Project Description Wind Turbine
Address Near 40th St SW & County Road 90
Applicant Name Trevor Beck
Applicant Address
Applicant Phone 774-571-5645
Email address
On Site Contact Ryan Januszewski
On-Site Contact Phone 763-287-5180
Declaration Licensed Contractor Declaration
Zoning Notes
Building Notes
Fire Notes
Zoning Approved 9/25/2015
Building Approved 9/25/2015
Fire Approved
Square Feet 0
Project Value 177251
Date Finaled
City Hebron
Parcel Number
Plan Review Fee 919.67
Inspection Fee 1414.88
Total Fee 2334.55
Fee Issue Date 9/24/2015
Sprinkler System Required
Occupancy Group U
Construction Type
Zone
Occupant Load
Status Closed
Assigned To Bobbi Strait

Uploaded Files		[Upload File]
Date	File	

Trevor Beck

From: North Dakota <wo@iworq.net>
Sent: Thursday, August 04, 2016 9:45 PM
To: Trevor Beck
Subject: North Dakota Permit # 150083

Follow Up Flag: Follow up
Flag Status: Flagged

This verifies Permit #15-0084S is closed and inspections have been completed. Should you have any questions, feel free to contact me for more information. I hope this is sufficient for your records. Bobbi Strait

Permit Information

Date 10/19/2015
Permit Number 150083
Stark Permit Number 15-083S
Permit Type Commercial
Date of Issuance 9/28/2015
Expiration Date
Project Title Sunflower Wind Project T-8
Project Description Wind Turbine
Address Near 40th St SW & County Road 90
Applicant Name Trevor Beck
Applicant Address
Applicant Phone 774-571-5645
Email address
On Site Contact Ryan Januszewski
On-Site Contact Phone 763-287-5180
Declaration Licensed Contractor Declaration
Zoning Notes
Building Notes
Fire Notes
Zoning Approved 9/25/2015
Building Approved 9/25/2015
Fire Approved
Square Feet 0
Project Value 177251
Date Finaled
City Hebron
Parcel Number
Plan Review Fee 919.67
Inspection Fee 1414.88
Total Fee 2334.55
Fee Issue Date 9/24/2015
Sprinkler System Required
Occupancy Group U
Construction Type
Zone
Occupant Load
Status Closed
Assigned To Bobbi Strait

Uploaded Files

[Upload File]

Date

File

Trevor Beck

From: North Dakota <wo@iworq.net>
Sent: Thursday, August 04, 2016 9:43 PM
To: Trevor Beck
Subject: North Dakota Permit # 150084

Follow Up Flag: Follow up
Flag Status: Flagged

This verifies Permit #15-0084S is closed and inspections have been completed. Should you have any questions, feel free to contact me for more information. I hope this is sufficient for your records. Bobbi Strait

Permit Information

Date 10/19/2015
Permit Number 150084
Stark Permit Number 15-084S
Permit Type Commercial
Date of Issuance 9/28/2015
Expiration Date
Project Title Sunflower Wind Project T-48
Project Description Wind Turbine
Address Near 40th St SW & County Road 90
Applicant Name Trevor Beck
Applicant Address
Applicant Phone 774-571-5645
Email address
On Site Contact Ryan Januszewski
On-Site Contact Phone 763-287-5180
Declaration Licensed Contractor Declaration
Zoning Notes
Building Notes
Fire Notes
Zoning Approved 9/25/2015
Building Approved 9/25/2015
Fire Approved
Square Feet 0
Project Value 177251
Date Finaled
City Hebron
Parcel Number
Plan Review Fee 919.67
Inspection Fee 1414.88
Total Fee 2334.55
Fee Issue Date 9/24/2015
Sprinkler System Required
Occupancy Group U
Construction Type
Zone
Occupant Load
Status Open
Assigned To Bobbi Strait

Uploaded Files

[Upload File]

Date	File
------	------

Trevor Beck

From: North Dakota <wo@iworq.net>
Sent: Thursday, August 04, 2016 9:52 PM
To: Trevor Beck
Subject: North Dakota Permit # 150085

Follow Up Flag: Follow up
Flag Status: Flagged

This verifies Permit #15-0084S is closed and inspections have been completed. Should you have any questions, feel free to contact me for more information. I hope this is sufficient for your records. Bobbi Strait

Permit Information

Date 10/19/2015
Permit Number 150085
Stark Permit Number 15-085S
Permit Type Commercial
Date of Issuance 9/28/2015
Expiration Date
Project Title Sunflower Wind Project T-49
Project Description Wind Turbine
Address Near 40th St SW & County Road 90
Applicant Name Trevor Beck
Applicant Address
Applicant Phone 774-571-5645
Email address
On Site Contact Ryan Januszewski
On-Site Contact Phone 763-287-5180
Declaration Licensed Contractor Declaration
Zoning Notes
Building Notes
Fire Notes
Zoning Approved 9/25/2015
Building Approved 9/25/2015
Fire Approved
Square Feet 0
Project Value 177251
Date Finaled
City Hebron
Parcel Number
Plan Review Fee 919.67
Inspection Fee 1414.88
Total Fee 2334.55
Fee Issue Date 9/24/2015
Sprinkler System Required
Occupancy Group U
Construction Type
Zone
Occupant Load
Status Closed
Assigned To Bobbi Strait

Uploaded Files		[Upload File]
Date	File	