

Hamre, John G.

From: Lein, Jerry R.
Sent: Monday, July 11, 2016 1:02 PM
To: Hamre, John G.
Subject: Fwd: ALLETE 250 kVDC Cass County Reroute , PSC Case No. PU-14-121
Attachments: FieldNotes_TransmissionLine.pdf; ATT00001.htm

John please docket.

Sent from my iPad

Begin forwarded message:

From: "Samantha N. Swanberg" <sswanberg@wenck.com>
To: "Lein, Jerry R." <jlein@nd.gov>
Cc: "Kevin J. Magstadt" <kmagstadt@wenck.com>
Subject: RE: ALLETE 250 kVDC Cass County Reroute , PSC Case No. PU-14-121

Jerry,

Attached are field notes for the ALLETE 250kV DC Trans Line PU-14-121.

Thanks,
Sam

From: Kevin J. Magstadt
Sent: Friday, July 08, 2016 3:42 PM
To: Lein, Jerry R.; Samantha N. Swanberg
Subject: RE: ALLETE 250 kVDC Cass County Reroute , PSC Case No. PU-14-121

We will provide yo you next week

Sent from my Verizon 4G LTE smartphone

----- Original message -----

From: "Lein, Jerry R." <jlein@nd.gov<<mailto:jlein@nd.gov>>>
Date: 7/8/16 2:42 PM (GMT-06:00)
To: "Kevin J. Magstadt" <kmagstadt@wenck.com<<mailto:kmagstadt@wenck.com>>>
Subject: ALLETE 250 kVDC Cass County Reroute , PSC Case No. PU-14-121
Kevin – Thank you for the construction inspection report filed June 7th in the above case. However, we have not yet received the corresponding field inspection notes required under the contract. Can you please provide? Thanks.

Jerry Lein
701 328-1035

32 **PU-14-121** Filed: 7/11/2016 Pages: 4
Field notes

Wenck Associates, Inc.
Samantha Swanberg

This transmission, email and any files transmitted with it, may be: (1) subject to the Attorney-Client Privilege, (2) an attorney work product, or (3) strictly confidential under federal or state law. If you are not the intended recipient of this message, you may not use, disclose, print, copy or disseminate this information. If you have received this transmission in error, notify the sender (only) and delete the message. This message may also be subject to disclosure under the North Dakota Open Records Laws.

May 26th Transmission line Rowcut

pt 426 - 2 pole trans line
minn Power #1391 GSA

pp65 Small mounds of dirt around
base structures potentially
from animals?

pt 427 - Mount, Disturbed area
from old structure

pp 74 no waste, little vegetation
- looking onto other end structure
- so disturbed area

pt 428 1-pole structure,
edge of field

pp 78
81

1391A

pt 429 - 2 pole structure 1391B
on-hillside/BS, veg around

pp 92 bases, small area of
cement waste between
bases, slightly uphill

pt 430 structure 13910
1-pole, cement base
pp 104 next to agr. field
between tree row
cut tree, stumps,

pt 431 2 pole structure
pp 117 13910, 95A6-19
very small amount concrete
waste around structure
small CFP ~~base~~ around base
agr. field edge