

NDPSC FIELD CHECKLIST AND NOTES

OBSERVER: Andrew Vistad

Project	Belle Fourche	Project No.	PSC No. PU-14-135 (HEI #146077-009)
Date	7/29//2016	SITE VISIT	7/18/2016

Site Visit Number and Observation Goals (i.e. 50% completed construction, as-built, reclamation etc.)

Final site visit for reclamation

Exclusion and Avoidance Areas / Siting and other Considerations for Visit

Confirm restoration activities have been completed and are establishing appropriately.

Check for erosion problems

Verify that construction debris has been cleaned-up.

Verify that fences have been repaired.

Verify that pipeline crossing roadways have been bored, roadways are stable.

Timeline of Activity on Site

Time	Activity
14:30 MDT	Arrive on site, Spoke with Don Clark
14:45 MDT	Observation along project.
17:30 MDT	Left Site

Photograph Log

1	Reclamation project beginning. Facing east.	9	Reclamation Facing South
2	Area lacking vegetation establishment. Facing North.	10	Reclamation Facing South East
3	Reclamation from center image to right side Facing North West.	11	Reclamation Facing North West.
4	Reclamation from center image to bottom. Facing North West.	12	Installed Fence repair and gate. Facing South East.
5	Reclamation through wetland. Facing South East.	13	Reclamation near valve Facing North West.
6	Reclamation of wetland. Facing West	14	Reclamation near valve Facing South East. End of project.
7	Reclamation of wetland. Facing East		
8	Reclamation of wetland pipe line runs from left to right across picture. Facing North.		



