

November 22, 2016

Ken Dockweiler
Director – Land Government and Compliance
Belle Fourche Pipeline Co.
455 North Poplar Street, PO Box 2360
Casper, WY 82602

RE: Post Construction Inspection, Case No. PU-14-135

Dear Mr. Dockweiler:

The North Dakota Public Service Commission retained a third-party vendor to conduct a post construction inspection under the authority provided in the above referenced case. Below we provide a weblink to the third-party post construction inspection report for your review and a link to the Commission's order in this proceeding.

We note that the third party inspector expressed concern regarding an influx of weeds along the construction route. Please provide the Commission an update as to the Company's efforts to control weeds and reseed on the route.

The construction report can be found at:
<http://www.psc.nd.gov/database/documents/14-0135/064-010.pdf>

The Commission Order can be found at:
<http://www.psc.nd.gov/database/documents/14-0135/029-040.pdf>

Please forward your response regarding weed control efforts and reseeding no later than July 31, 2017.

If you have any questions regarding this letter, please contact me at 701-328-4153.

Sincerely,


Sara Cardwell
Public Utility Analyst