

| | | | | |
|-------------------------------------|-----------------|-----------------------|--------------|--------------|
| Weekly Construction Progress Report | | KINDER MORGAN | | |
| | | Week of: June 8, 2015 | | |
| Case No. PU 14-840 | | | | |
| | Name | Company | Office | Cell |
| Project Manager | Jason Hartman | Hiland Crude | 713.420.7796 | 903.472.8055 |
| Chief Inspector | Daniel McCarthy | Onshore | 318.355.2224 | |

| | | | |
|---|------------|-------------|------------|
| Brief Description of Weekly Activities: | | | |
| Construction work continued; trenching, bending and setup, stringing, mainline welding, field joint coating, lowering in pipe, backfill, and cleanup continued. | | | |
| Specific Activity on Project | | | |
| Description | % Complete | Description | % Complete |
| Potholing | 100% | | |
| Fencing Gaps | 100% | | |
| Clearing | 100% | | |
| Grading | 100% | | |
| Trenching | 98% | | |
| Bend and setup | 98% | | |
| Stringing | 98% | | |
| Mainline Welding | 98% | | |
| Field Joint Coating | 98% | | |
| Lowering in Pipe | 98% | | |
| Backfill | 98% | | |
| Rough clean up | 3% | | |
| Significant Work Activity for next Week: | | | |
| Continue trenching, bending, stringing, welding, field joint coating, lowering in, backfill and rough clean up. | | | |

| |
|------------------|
| Comments: |
| |

| | |
|-------------|-------------|
| Name | Date |
| Megan Mater | 6/11/2015 |