

PU-14-840

PU-13-136

July 27, 2016

Hiland Kinder Morgan
Rep: Myles Fisher

pt 1 - Dore terminal
sign broken

pp 298
343

- GPS not working / no
point - very end of terminal / purple

pt 2 - Cross irrigation line
in crop field

pp 304
349

Bored Canal
- fenced area

pt 3 - wheat field
- small undulation in
the field - Did not
notice subsidence
maybe in a different area?

pp 308
353
354

- Said landowners were happy
- Bore location

- Corps land w/ sign

for River Bore
no work done the only sign

pt 4 - thru field
- some dirt in veg.

pp 311
359
358
- Bare under trees & Road
& thru hill

pt 5 - reseeded in Spring
orig - July

362
pt 6 - Slender whorlgrass
& weeds
310
361

pt 7 - Veg growing
Some weeds

323
368
- Erosion Control
Blanket

pt 8 - Some grasses & weed
Sandy soil
327
372
- Mowed Area - end of June
Seeded fall & Spring
- Mowed in easement
& (Lands) - her. (comp) ext.

pt 9 - Alfalfa field

377-380⁺ looks good

PP331

370 - 380

pt 10 - Dore Junction

PP335 - Berm to stop

380

storm water

384

runoff to
firmus field

pt 11 - Row turn field
Wood Marker

PP337

384
84

pt 12 - field - good Veg growth
Pasture land

PP341

391

Seeded 3 yrs ago?

Double Ditching (early on)

pt 13

Row @ Hwy 88^N
- few sign heads

PP 343

344

- unsure what stable
bean area is - other
P/L - water, or part of
field

PP 345

346

pt 14

West
- Camp Creek Injection

PP 349

- field

pt 15

- Signs
thru field

PP 350

pt 16

Row cattle an area
tall grass

PP 353

valve on one side
shut land on other?

pt 17

- east Camp Creek injection
multiple lines

PP 356

405

- have done best
Reclamation work in area

pt 18

PP 358
U10

pt 19

PP 361
U10

pt 20

PP 363
U12

pt 21

22

PP 365-67

Wattford Injection Stakes
line behind parallel to River

Road Crossing
- Construction nearby
- flags
- other line ROW

- Grass, clover, alfalfa
& weeds growing
- can see stone

trees
- Slope Area, Redd. Ho.
partly Reseeded Spring 2015
- top soil laid in year
before

- weeds - thistle
- tree Area

410

7-28-2016

pt 23

- near River Crossing

pp 370

Valve Station

417-419

- Ag Irrigated field

pt 24

- line Crossing thru

pp 373

Ag fields

pt 25

- Highway Crossing ^{# 64}

pp 376

- w/ signs

424

pt 26

- gravel road Crossing
in Ag. fields

pp 378

427

pt 27

Road Crossing

pp 380

Ag field

429

pt 28 - multiple lines

pp 387 - flagged
- through field

431-437 - off of Highway

pt 29 - Gravel Road cross. v
going thru fields

pp 391
440 Near other pipeline
being put in
- some weeds

pt 30 - unknown if trees
removed or bored

394
440-441 - DAPL Parcelling
- fields

431
- Ag fields

pp 397
445-447
- signs

pt 32
pp 398
448

- ^{Ag} field
- Sign

pt 33

pp 399
449

- Sign Marker
- Pin flags
- field

pt 34

450-454

- McGonally Rowley?
- slight scare
- Ag field

pt 35

pp 407

455-457

- where line comes
back in

pt 36

pp 409
458

- Signs
- Ag field
- unknown if buildings
is theirs

pt 37

pp 411

460

- White Earth Booster
multis lines