



Bridger Pipeline LLC
PO Drawer 2360
Casper WY 82602

January 26, 2017

Sara Caldwell
Public Utility Analyst
Public Service Commission – North Dakota
600 East Boulevard
Dept. 408
Bismarck ND 58505



RE: Post Construction Inspections PU-15-97

Bridger Pipeline offers the following responses to your August 28th 2015 letter in regard to the post construction inspection of the above captioned order. The responses correspond in order with the bullets of your letter.

- Establishment of Vegetation and Reclamation Process – Although Bridger has completed the initial reclamation phase we will have to wait for spring in order to confirm that revegetation has been achieved. In order to allow a legitimate review of the progress made towards revegetation Bridger will review the project area once the growing season gets underway and will provide an update to your office by July 31, 2017.
- As-built files – Please find included in this mailing, a CD with the as-built files on it. Hard copies of the alignment sheets will be shipped separately and should arrive within a few days of this mailing.
- Tree and Shrub impact – Bridger has not been able to confirm that we were able to avoid impact to the limited number of trees and shrubs that were in the construction corridor. Bridger plans to do this evaluation as soon as we are able to traverse the right-of-way when the snow clears, and will respond in writing at that time.
- Sign Markers – All sign markers along the pipeline route have been installed as of the writing of this letter.

Feel free to contact Ken Dockweiler directly at 307-266-0275, if you need any further information or if you have any questions.

Sincerely,

Tom Litman
Land Supervisor

CC: Bob Dundas
Hank True
Tad True
Manuel Lojo

54 **PU-15-97** Filed: 1/31/2017 Pages: 6
Response to 21 Nov. 2016 letter re post construction inspection report

Bridger Pipeline LLC

Tom Litman, Land Supervisor