



two of four
10' by 10'
box culverts
under
construction

erosion
feature

low flow (60")
culvert outlet

Shop Access Road

low flow (60")
culvert inlet

Coyote Creek

Still frame of the June 25, 2015 Public Service Commission flyover inspection video of the Shop Access Road in Coyote Creek Mine Permit NACG-1302 in relation to Coyote Creek culvert crossings.

ND Public Service Commission August 27, 2015