



Public Service Commission
State of North Dakota

COMMISSIONERS

Randy Christmann
Julie Fedorchak
Brian Kroshus

Executive Secretary
Darrell Nitschke

April 28, 2017

600 East Boulevard, Dept. 408
Bismarck, North Dakota 58505-0480
Web: www.psc.nd.gov
E-mail: ndpsc@nd.gov
Phone: 701-328-2400
ND Toll Free: 1-877-245-6685
Fax: 701-328-2410
TDD: 800-366-6888 or 711

John W. Morrison
Crowley Fleck Attorneys PLLP
100 West Broadway, Suite 250
Bismarck, ND 58502-2798

**RE: Oasis Midstream Services LLC
10.75-inch Crude Oil Pipeline – McKenzie County
As-Built Construction Inspection
Case No. PU-15-733**

Dear Mr. Morrison:

The North Dakota Public Service Commission retained a third-party vendor to conduct an as-built construction inspection under the authority provided in the above referenced case. Below we provide a weblink to the third-party as-built construction inspection report for your review and a link to the Commission's order in this proceeding. We note that the third party inspector expressed concerns in its inspection regarding two areas (approximate stations 753+00 and 931+00) that showed rutting (Photos 9 and 12) and one area (approximate station 960+00) with rocks (Photo 13).

The construction report can be found at:
<http://www.psc.nd.gov/database/documents/15-0733/069-010.pdf>

The Commission Order can be found at:
<http://www.psc.nd.gov/database/documents/15-0733/031-040.pdf>

Please have the Company review each of the photographs in the as-built construction inspection report. Please provide updated pictures of each area demonstrating that the rutting has been fixed and the rocks have been removed no later than July 31, 2017.

If you have any questions regarding this letter, please contact me at 701-328-4153.

Sincerely,

Sara Cardwell
Public Utility Analyst