



6/27/2017

Oasis Petroleum
1001 Fannin St.
Suite 1500
Houston, TX 77002



Sarah Caldwell
Public Utility Analyst
Public Services Commission
600 East Boulevard Avenue Dept. 408
Bismarck, ND 58505-0480

RE: Oasis Response to Public Services Commission Letter; Case No. PU-15-733; As-Built Construction Inspection: Updated ROW pictures

Oasis respectfully submits this letter and attached photographs to show rocks have been removed from site marker 960+00 and rutting issues addressed at site markers 753+00 & 931+00 as described in the third party inspector's As-Built Inspection Report.

Please, do not hesitate to contact me if there are any additional questions or concerns regarding this matter at 713-770-6430.

Best Regards,

David Copeland


David Copeland
Regulatory Specialist II
Oasis Petroleum

Pictures

1. Station 753+00 (before & after)



2. Station 931+00 (before & after)



Pictures

3. Station 960+00 (before & after)

