

April 12, 2017

Patrick Fahn
ND Public Service Commission
600 E. Boulevard Ave.
Bismarck, ND 58505-0480



Re: As Built Construction Inspection Report
for Sacagawea Pipeline Company, LLC
Johnson's Corner Connector Crude Oil Pipeline Project
McKenzie County
PU-15-744

Dear Mr. Fahn:

Enclosed are four (4) signed copy for the As Built Construction Inspection report as complied by KLJ. This report covers work done regarding As-Built requirements on right of way easement, for Johnson Corner Connector Crude Oil Project, PSC case number PU-15-744. Also provided is one (1) electronic copy of the report on thumb drive for the project. The thumb drive also includes original site inspection photos.

You can reach me at the office at (701) 355-8786 or my cell phone 425-4514. My email is arnie.siverson@kljeng.com if you have any additional questions or comments.

Sincerely,

KLJ

Arnie Siverson
Environmental Field Inspector

Enclosure(s): Johnson's Corner Connector Crude Oil Pipeline Project, 4 signed copies;
1 Thumb Drive