

1. Project Overview

Project Managers: Clay Anderson
Project Location: SOR, Keene ND

2. Project Status

2.1. Performance Indicator Explanation

- Safety: N/A
- Schedule: N/A
- Quality: Additional programming required due to oil cooler requirements

3. Summary of Progress

3.1. Key Accomplishments since last reporting

- 26-Aug
Booster Skid I/E installation
- 27-Aug
Booster Skid I/E installation
- 28-Aug
Booster Skid I/E installation
- 29-Aug
Skid QA walkdown, no major finding
- 30-Aug
Skid QA walkdown, no major finding.

3.2. Major Activities Planned for next reporting

- Skid shipment & Offload
- Commence Phase II onsite construction