



- Imagery Source: USDA-FSA-APFO
Aerial Photography Field Office
- Milepost
 - New Alignment
 - Previous Alignment
 - Project Corridor
 - Section Boundary
- Avoidance Areas**
- Abandoned Mine
 - Potential for Future Slope Instability
 - Occupied Structure within 500' of Route
 - Occupied Structure (500' Buffer)
 - Landslide Deposits
 - National Grassland

**ONEOK Bakken Pipeline, L.L.C.
Demicks Lake Pipeline Project**

Project Alignment Adjustments

Exhibit A

McKenzie County, ND



Source: Z:\Clients\W_P\Oneok\Demicks_Lake_Pipeline\Permitting\PS\201907\Figures\ULP_PSC_Supplemental_Route_Modifications_20190804.mxd