



Exhibit A



- Imagery Source: USDA-FSA-APFO
Aerial Photography Field Office
- Milepost
 - New Alignment
 - ▭ Project Corridor
 - ▭ 1-Mile Study Area
 - ▭ Section Boundary
- Avoidance Areas**
- ▲ Abandoned Mine
 - ⬡ Potential for Future Slope Instability
 - ⬡ Occupied Structure within 500' of Route
 - ⬡ Occupied Structure (500' Buffer)
 - ⬡ Landslide Deposits
- *No exclusion areas within vicinity of Project

Exhibit A
ONEOK Bakken Pipeline, L.L.C.
Little Missouri Lateral Pipeline Project
Project Alignment Adjustments
 McKenzie County, ND

 For Environmental Review Purposes Only 7/23/2019

Source: Z:\Clients\MT_P\Oneok\Little Missouri Lateral\Permitting\PS\201907\Figures\TML_PSC_Supplemental_Route_Modifications_20190723.mxd